



**2024  
BYD SEAL 06**



# 2024 BYD SEAL 06

## PERFORMANCE

- 5-Seater DM-I PHEV
- 2,100 km Hybrid Range
- 120 km EV Range
- 16-inch Tires

## FEATURES

- 8.8-inch LCD Instrument Screen
- 15.6-inch Rotating Center Screen
- Leather Interior
- Automatic Air Conditioning
- 8-Speaker Sound System
- Adaptive Cruise Control
- Bluetooth Phone Set
- Power Locks, Mirrors
- Auto-Hold
- Engine Start/Stop
- 6 Airbags
- Lane-Keep Assist, Blind Spot Detection
- Daytime Running Lights
- Rear AC Vents









BYD

ALWAN 4 DQ  
الوان 4 دق

ERANGE Performance

SAILUN





BYD

ALWAN / آلوان





































BYD

AIRBAG

模式

\*

复位+

设定-

5  
kW

distance refuel

km/h

HEV

6 km



217 4830

04:38 PM

NORMAL HEV P

28°C

请您在使用产品时，  
Please remove the protective film.

AS

5 kW

km/h

Please refuel

AI-EM

0 km OK 228 km

HEV 6 km

The image shows a digital instrument cluster (DIC) in a car. The display is framed by a steering wheel. At the top left, there is a QR code and the number '217 4830'. The time '04:38 PM' is displayed in the top center. The driving mode 'NORMAL HEV P' is shown in the top right. The temperature '28°C' is in the top right corner. A warning message in Chinese and English is at the top right: '请您在使用产品时， Please remove the protective film.' The center of the display features a large fuel pump icon and the text 'Please refuel'. To the left of the center, there is a '5 kW' power indicator. To the right, there is a 'km/h' speed indicator. At the bottom, there are two battery level indicators: 'AI-EM' on the left and 'HEV 6 km' on the right. The 'AI-EM' indicator shows a range of '0 km' and 'OK', while the 'HEV' indicator shows a range of '228 km'.



HKHB-7924100AB-PAD 显示屏总成  
040J5303ZR91270360

请您在使用产品前将产品保护膜撕掉!  
Please remove the protective film before using!

4:38 PM

7m 0°

你可以这样说:  
你好小迪, 播放音乐

番禺区  
Sunny 31°C

Video  
No video

Kuwo  
我记得

Amap Auto Custom

Ximalaya



< Lo >



< 488 >



















































**ATTENTION**  
Please do not touch the  
internal components of the  
charging port. Contact with  
the internal components may  
cause an electric shock.  
Please refer to the user manual  
for more information.













BYD

比亚迪  
DM-i

海豹06

ALWAN / الوان





BYD

海豹 06

ALMAN ٤١٩٠